



LEGENDS

- s** : Width across flats
- e** : Width across corners
- m** : Height of the Nut
- d** : Nominal Diameter fo thread

Thread d		M1.6	M2	M2.5	M3	M4	M5	M6	M8	M10	M12
P		0.35	0.4	0.45	0.5	0.7	0.8	1	1.25	1.5	1.75
c	max.	0.2	0.2	0.3	0.4	0.4	0.5	0.5	0.6	0.6	0.6
	min.	0.1	0.1	0.1	0.15	0.15	0.15	0.15	0.15	0.15	0.15
da	max.	1.84	2.3	2.9	3.45	4.6	5.75	6.75	8.75	10.8	13
	min.	1.6	2	2.5	3	4	5	6	8	10	12
dw	min.	2.4	3.1	4.1	4.6	5.9	6.9	8.9	11.6	14.6	16.6
e	min.	3.41	4.32	5.45	6.01	7.66	8.79	11.05	14.38	17.77	20.03
m	max.	1.3	1.6	2	2.4	3.2	4.7	5.2	6.8	8.4	10.8
	min.	1.05	1.35	1.75	2.15	2.9	4.4	4.9	6.44	8.04	10.37
mw	min.	0.8	1.1	1.4	1.7	2.3	3.5	3.9	5.2	6.4	8.3
s	nominal = max.	3.2	4	5	5.5	7	8	10	13	16	18
	min.	3.02	3.82	4.82	5.32	6.78	7.78	9.78	12.73	15.73	17.73

Thread d		M16	M20	M24	M30	M36	M42	M48	M56	M64	-
P		2	2.5	3	3.5	4	4.5	5	5.5	6	-
c	max.	0.8	0.8	0.8	0.8	0.8	1	1	1	1	-
	min.	0.2	0.2	0.2	0.2	0.2	0.3	0.3	0.3	0.3	-
da	max.	17.3	21.6	25.9	32.4	38.9	45.4	51.8	60.5	69.1	-
	min.	16	20	24	30	36	42	48	56	64	-
dw	min.	22.5	27.7	33.3	42.8	51.1	60	69.5	78.7	88.2	-
e	min.	26.75	32.95	39.55	50.85	60.79	71.3	82.6	93.56	104.86	-
m	max.	14.8	18	21.5	25.6	31	34	38	45	51	-
	min.	14.1	16.9	20.2	24.3	29.4	32.4	36.4	43.4	49.1	-
mw	min.	11.3	13.5	16.2	19.4	23.5	25.9	29.1	34.7	39.3	-
s	nominal = max.	24	30	36	46	55	65	75	85	95	-
	min.	23.67	29.16	35	45	53.8	63.1	73.1	82.8	92.8	-